




FIG. 1





F I G . 2



PRIORITY	SECOND SWITCHING UNIT	THIRD SWITCHING UNIT	FOURTH SWITCHING UNIT
"1"	b	d	f
"2"	c	e	g

(CLOCK SUPPLY LINE PRIORITY TABLE)

F I G . 4

(CLOCK SUPPLY LINE FAULT DETECTION PROCESSING)




FIG. 5

(AIS OAM CELL TRANSMISSION PROCESSING)






FIG. 6

(CLOCK SUPPLY LINE SWITCHING PROCESSING)



F I G . 7

(RDI OAM RECEPTION PROCESSING)



F I G . 8

FIG. 9





FIG. 10

(CLOCK SUPPLY LINE PRIORITY TABLE)

PRIORITY	SECOND SWITCHING UNIT	THIRD SWITCHING UNIT	FOURTH SWITCHING UNIT	FIFTH SWITCHING UNIT	SIXTH SWITCHING UNIT	SEVENTH SWITCHING UNIT
"1"	b	d	f	h	j	h
"2"	c	e	l	0	k	i
"3"	m				p	



F I G. 11
PRIOR ART